

Specifications

Electronic Inclinometers with Remote Display

Remote Display

- 1 No

Display Units	: mm/m, arcsec, deg
Digital Interface	: RS232 / RS485
Display Update Rate	: 3 values/sec minimum
Wireless Interface	: Bluetooth
Wireless Range	: 10 m
Simultaneous Display	: 2 Inclinometers maximum
Power Supply	: Internal Battery & External Adapter
Operating Temperature	: 0 °C to + 40 °C
CE conformity	: Shall meet emission and immunity requirements
Supplied Accessory	: Battery, Carrying Case, RS485 Cable

Note : Internationally Traceable Calibration Certificate has to be supplied along with the item

Warranty : To be clearly spelt out in the offer. Preferably 12 Months or More from the date of acceptance of the item at our site.